

# High Temperature IR Thermometer

✓ Measures surface temperature up to 1400°F (760°C)  
With built-in Laser Pointer that identifies target area and improves aim

## Features:

- High temperature range from -58° to 1400°F (-50 to 760°C)
- 16 to 1 distance to target ratio measures smaller surface areas at greater distances
- Adjustable high/low alarm alerts user visually and audibly when temperature exceeds programmed limits
- Adjustable emissivity for better accuracy on different surfaces
- MAX/MIN/AVG/DIF features display highest, lowest, average, and MAX minus MIN values
- Large backlit display
- Laser pointer identifies target area
- Automatic Data Hold
- Automatic Power Off
- High Resolution of 0.1° up to 199.9°
- Complete with 9V battery and hard carrying case



Laser pointer identifies target area.

## Specifications

Range	-58 to 1400°F (-50 to 760°C)
Basic Accuracy	±2%rdg or 4°F (2°C) <932°F (500°C); ±(2.5%rdg + 5°)>932°F (500°C)
Max. Resolution	0.1°F/°C
Emissivity	0.1 to 1.00 Adjustable
Field of View (Distance to Target)	16:1
Dimensions	3.9 x 2.2 x 9" (100 x 56 x 230mm)
Weight	10.2oz (290g)

## Ordering Information:

42540 .....High Temperature IR Thermometer  
42540-NIST .....42540 with Calibration Traceable to NIST.

**CALRIGHT**  
**INSTRUMENTS**

The Right Source For Your Test & Measurement Needs

8715 Mesa Point Terrace San Diego, CA 92154  
Toll Free: 1.866.363.6634 Tel: 1.619.429.4545 Fax: 1.619.374.7012  
Email: sales@calright.com <http://www.calright.com>